

# ELEC2400 Lab1b Preparation


1. You should put the two AA battery into the multimeter. You might need a screwdriver to open case. Please remember to turn it off afterwards.



2. You should prepare 4 AA battery (rechargeable/ Alkaline)



AA Alkaline Battery  
(any brand name)



AA Rechargeable Battery  
(any brand name)

3. You need to plot a curve (x-axis is log scale, y-axis is normal scale). You might use other software to plot it, like Excel. Or you could do the plotting in Word, you could refer to the video clip to learn how to do that.

Canvas (Elec2400) -> Lab Material -> 4) Plot the curve in WORD (mp4)